Annexure D

	7.11.10.7.1.0						
BUILDING SAFETY CERTIFICATE							
No. C-25				Dated:			
It is certified that the	existing buil	ding SH.R.I.J	URGA SHIK	SHA. HIKE	JAN PUNTA	me of the	
building or premises) at .	DEVRI	RUKHA	RA, BAK	SHI KAJ	ALAB,L	YCKNOW	
(address) is having block(s)/Floor(s) as per details below:							
Detail of Block(s) in	Block	Block	Block	Block	Block	Block	
school	(1)	(2)	(3)	(4)	(5)	(6)	
No. of Floor(s) in the	Ground Al						
Block	first Floor				Landing the state of the state	_	
The building is owned/occupied by Shr LL DURGA SHINSHA NIKETAN PURLIC SCHOOLD ame							
of the Institution) have complied with the Building safety requirements in accordance with National							
Building code Rules, and verified by the officers concerned of Linguisting Length (Name of							
Department/ Govt.) on(date of inspection) in the presence							
of Mr. Krishna Murari, Vipul Khanl Gouti Ngul (Harne and addresses of the							
Manager/Secretary or his representative) and that the building/premises is fit for occupancy for							
running school with effect from192.4. for a period of5. (
with rule and subject to compliance of the specific conditions as appended.							
1. III floor construction is not suggested.							
2. Maintenace will be required always. 3. Natural climatins beyond this centificate.							
4.	•	7000	,,,,	2.9,200	•		
Issued on 19.8.24 at Luckhow by							

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Designation : A

Name & Address of Department Office Rural Engineering Department Division, Lucknow